


Supertech Handling & Storage

Painted **Supertech** boards are coated to the face and four edges only. Please read the instructions below before you offload this product.



Unsafe Handling

To prevent damage do not drag the boards off the pallet.



Safe Handling

Lift boards clear of the pallet to prevent scratching. Always carry or lift the boards on their sides with 2 persons.



In-efficient Stacking

Stacking without the foam interleave will cause damage to the surface.



Efficient Stacking

Always replace foam interleave when re-stacking to protect the finish from damage.



Poor Storage

Allowing the uncoated surface to get wet will cause damage.



Protective Storage

Keep dry at all times during site storage and fixing.